



**Toyota Motor Engineering &  
Manufacturing North America, Inc.**

Vehicle Safety & Compliance  
Liaison Office  
Mail Code: S-104  
19001 South Western Avenue  
Torrance, CA 90501

July 14, 2016

Mr. Gregory K. Rea  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Attn: Recall Management Division (NEF-100)  
1200 New Jersey Ave, SE  
Washington, D.C. 20590

Re: Foreign Safety Recall/Other Safety Campaign Report  
Certain Toyota Vehicles

Dear Mr. Rea:

In accordance with 49 CFR 579.12, attached is a copy of our Foreign Safety Recall/Other Safety Campaign Report for the subject vehicles.

Should you have any questions about this report, please contact me directly.

Sincerely,

Abbas Saadat  
Vice President  
Vehicle Safety & Compliance Liaison Office  
Toyota Motor Engineering & Manufacturing  
North America, Inc.

Enclosures  
Foreign Safety Recall/Other Safety Campaign Report

Date: July 14, 2016

**Foreign Safety Recall / Other Safety Campaign Report**

Subject: Replacement headlamp issue on certain Toyota Auris vehicles

1. Vehicle Manufacturer Name:

Toyota Motor Manufacturing UK Ltd. ["TMUK"]

2. Involved Vehicles:

Make/ Car Line	Model Year	Country/Region	Action	Production Period	Number of Vehicles
Toyota / Auris, Auris HV	*1	Europe, Turkey, Israel, Morocco, Singapore	Safety Recall: Europe Other Safety Campaign: Other countries	October 2012 through April 2015	247

\*1: Most other countries/regions do not use a model year designation.

3. Substantially Similar Vehicles sold in the U.S.:

Model Year/ Make/ Car Line:	2012 - 2015 Model Year	Toyota Prius, Prius V, Scion tC, Scion xB
		Lexus CT
	2012 Model Year	Lexus HS

4. Description of Problem:

The headlamp assembly specified as a replacement Toyota Genuine Service Part was incorrectly assigned to the subject vehicles due to an incorrect entry of the part number in the service part system. If a subject vehicle uses an incorrectly identified service headlamp as a replacement part, the luminous intensity distribution may be different than designed. Improper luminous intensity distribution could result in noncompliance with ECE48 "Installation of Lighting and Light-Signaling Devices", and temporarily impair the vision of drivers operating oncoming vehicles, which could increase the risk of crash.

5. Description of Corrective Repair Action:

For all affected vehicles, dealers will replace the incorrect headlamp assembly with a correct one.

6. Determination to Conduct Safety Recall / Other Safety Campaign:

- The determination was made by Toyota Motor Corporation;
- Date of determination : July 8, 2016
- Date campaign will commence : Late July, 2016

7. Reason the similar vehicles sold in the U.S. are not involved in this safety recall / other safety campaign:

This issue only affects the above mentioned Toyota Auris vehicles which were produced at TMUK and received replacement headlamp(s) after the point of first sale. Substantially similar vehicles sold in the U.S. use different headlamp designs with different service part numbers. None of the involved vehicles and headlamps have been exported to or sold in the U.S.